**Fox Valley Metrology**
3114 Medalist Drive
Oshkosh, WI 54902
(920) 426-5894 • Fax (920) 426-8120
https://www.FoxValleyMetrology.com

# CERTIFICATE OF CALIBRATION

ACCREDITED
ISO/IEC 17025
CALIBRATION AND DIMENSIONAL MEASUREMENT
Certificate No. ACT-1272

| | |
|---|---|
| **CERTIFICATION NUMBER** | CP134-00065-840 |
| **FOR** | Sample Manufacturing<br>3121 Medalist Drive<br>Oshkosh, WI 54902 |
| **TEST INSTRUMENT** | Sand Testing<br>Rapid Sand Washer |
| **MAKE** | Simpson+Gerosa |
| **MODEL** | 42119 |
| **CUSTOMER LOCATION** | Location1<br>Location2 |
| **CONDITION RECEIVED** | In Tolerance |
| **CONDITION RETURNED** | In Tolerance |
| **CALIBRATED BY** | Chris Strehlow |
| **REVIEWED/ISSUED** | D.P. 07/29/2025 |
| **CALIBRATION LOCATION** | FVM |
| **ENVIRONMENT** | 69.0°F, 31.0%RH, 28.92inHg |
| **CALIBRATION DATE** | 05/14/2025 |
| **RECALIBRATION DUE** | 05/14/2026 |

| | |
|---|---|
| **IDENTIFICATION** | MC-028A |
| **SERIAL NUMBER** | 65 |
| **PURCHASE ORDER #** | |

**PROCEDURES FOLLOWED**

MC-028A rev. 1

**STANDARDS USED**

| INSTRUMENT | SERIAL NUMBER | TRACE NUMBER | NEXT CAL |
|---|---|---|---|
| FVR-197A | FVR-197A | CO083-37408-690 | 07/31/2025 |
| FVS-422A | | CP093-47769-540 | 04/30/2026 |

## CALIBRATION RESULTS

* DENOTES "OUT OF TOLERANCE"

| FEATURE | NOMINAL | LOWER LIMIT | UPPER LIMIT | AS FOUND | AS LEFT | UNCERTAINTY |
|---|---|---|---|---|---|---|
| TImer | (s) | (s) | (s) | (s) | (s) | (s) |
| @5 min | 300.00 | 295.00 | 305.00 | 300.15 | 300.15 | 5.8E-1 |
| @5 min | 300.00 | 295.00 | 305.00 | 300.21 | 300.21 | 5.8E-1 |
| @5 min | 300.00 | 295.00 | 305.00 | 300.18 | 300.18 | 5.8E-1 |



**COMMENTS**

Example certificate, actual results and uncertainties will be reported at the time of calibration.
Nominal and limits may vary based on actual make/model.